

939 se alder st . portland, or . 97214 [503]445.4368 www.speedymoto.com

Installation Instructions

06-0225 SpeedyMoto Clutch Springs + Caps Kits

Parts included

- 1. Six stainless steel springs
- 2. Six aluminum caps
- 3. Six stainless steel bolts

Tools required

- 1. 4mm Allen wrench/torque wrench adapter
- 2. Torque wrench

Installation

- 1. Remove clutch cover.
 - Note: Take note of the positions of the different-length bolts, as they will need to be reinstalled in their original positions.
- 2. Remove the 6 bolts retaining the spring retention caps and springs.
- 3. Replace the stock caps and springs with the SpeedyMoto cap and springs.
- 4. Install the SpeedyMoto stainless steel bolts. Torque all six bolts to 5 Nm (~3.7 Ft. Lbs.).
- 5. Reinstall clutch cover.
- 6. Ride it, and tell all your friends about SpeedyMoto!



939 se alder st . portland, or . 97214 [503]445.4368 www.speedymoto.com purveyors ºf fine speed metal

Installation Instructions

06-0225 SpeedyMoto Clutch Springs + Caps Kits

Parts included

- 1. Six stainless steel springs
- 2. Six aluminum caps
- 3. Six stainless steel bolts

Tools required

- 1. 4mm Allen wrench/torque wrench adapter
- 2. Torque wrench

Installation

- 1. Remove clutch cover.
 - Note: Take note of the positions of the different-length bolts, as they will need to be reinstalled in their original positions.
- 2. Remove the 6 bolts retaining the spring retention caps and springs.
- 3. Replace the stock caps and springs with the SpeedyMoto cap and springs.
- 4. Install the SpeedyMoto stainless steel bolts. Torque all six bolts to 5 Nm (~3.7 Ft. Lbs.).
- 5. Reinstall clutch cover.
- 6. Ride it, and tell all your friends about SpeedyMoto!